

AIR CHAMP® PRODUCTS

Product Change Notice



Dear Customer,

Nexen Group, Inc. has recently changed the color code painted on the friction material of this brake. The base compound is the same, and the brake performance is the same; only the color code has changed. The new color (red) is being used because it better reflects the material's coefficient of friction.

Previous Color	Purple	Nexen's code for High Coefficient of Friction
New Color	Red	Nexen's code for Standard Coefficient of Friction

The friction material on this brake has always had a standard coefficient of friction, so the color change simply reflects the actual coefficient of friction produced by this friction material.

This change only effects certain SPC and BD brakes that use this friction material; itdoes not apply to other Nexen products. If you have any questions, please call our customer support group at 800-843-7445.



Nexen Group, Inc. 560 Oak Grove Parkway Vadnais Heights, MN 55127 800.843.7445 Fax: 651.286.1099 www.nexengroup.com

ISO 9001 Certified